

WESTRAC WA SOS Lab - 128 Great Eastern Highway (next to Institute)

South Guildford, WA 6055 AUS

PHONE: (08) 9377 9521



Web: www.westrac.com.au Email: soslab.wa@westrac.com.au

TRANSMISSION POWER

SHIFT

T08P-54164-1722

SAMPLE SHIP TIME (days): 7


CAPE MINING

CAPE MINING_118

BODDINGTON

RECEIVED DATE: 12-Jun-24

EQUIP NUM: CWT22



Action Required

SERIAL NUMBER: A40DV13733

Interp By: Steve De Boer Interpreted On: 14-Jun-24

S.O.S WEB

30.2

Suggest check the filters and the magnetic screen for wear The copper concentration is high. The copper is possibly leaching from the cooler core. As this oil has been changed, Resample to confirm any contaminants. The oil viscosity (V40) is lower than the specification for the reported oil. Check the type and maintenance, adjustments or repairs, grade of the new oil. Please advise if any amendment or correction is required. Possible incorrect oil type reported. For all sample information update requests, SOS Lab on (08) 9377 9521. For Steve de Boer on (08) 9377 9575.

VISCOSITY (Centistokes)

Viscosity at 40 C

V40

		SAMPLE INFORMA	TION
	\triangle	1	1
Sampled Date	05-Jun-24	30-Mar-23	30-Jun-20
Sample Id	T08P-54164-1722	T08P-53095-0436	T08P-50185-3300
Lab Date	12-Jun-24	05-Apr-23	03-Jul-20
Meter [Hr]	14038.0	13466.0	12930
Comp Meter [Hr]	14038.0	13466.0	
Meter On Fluid	1108.0		430
Fluid Brand	CALTEX	MOBIL	CALTEX
Fluid Weight	50	30	UNKNOWN
Fluid Type	DELO SYNTHETIC TR	MOBILTRANS HD	TEXAMATIC1888
Fluid Change	Υ	N	Υ
Filter Change	Υ	N	Υ
	0	0	

ADDITIVES-WEAR LEVELS

T NEVIOUS SAWII EE
The oil viscosity (V40) is lower than the specification for the reported oil. This along
with differences in the additive pack indicate incorrect oil details reported. The copper
is possibly leaching from the cooler core. Monitor this in following samples for
changes. The iron,, aluminium and tin are slightly high. Suggest, inspecting
magplug/filter media and/or screens for wear metal and contaminants. All other test
results appear satisfactory, continue to sample at regular intervals. For technical
enquiries regarding this evaluation , please contact Richard Scott on (08) 9377 8703 .

For additional sample history, go to:

PREVIOUS SAMPLE

		CONDITION-CONTAMINATION			
		05-Jun-24	30-Mar-23	30-Jun-20	
OIL C	ONDITION				
OXI	Oxidation	13	13	13	
SUL	Sulfur Products	19	19	20	
NIT	Nitration	4	3	3	

		ADDITIVI	=S-WEAR LE		
		05-Jun-24	30-Mar-23	30-Jun-20	
ELEM	IENTS (PPM) ASTM D5185				
Cu	Copper	348	273	219	
Fe	Iron	32	24	20	
Cr	Chromium	<1	<1	<1	
Al	Aluminum	11	8	5	
Pb	Lead	3	3	2	
Sn	Tin	15	11	8	
Si	Silicon	2	2	2	
Na	Sodium	7	6	3	
K	Potassium	1	1	1	
Мо	Molybdenum	<1	<1	<1	
Ni	Nickel	<1	<1	<1	
Ag	Silver	<1	<1	<1	
Ti	Titanium	<1	<1	<1	
V	Vanadium	<1	0	<1	
Mn	Manganese	<1	0	<1	
Cd	Cadmium	0	0	<1	
Ca	Calcium	18	17	19	
Р	Phosphorus	203	186	179	
Zn	Zinc	7	6	7	
Mg	Magnesium	2	1	4	
Ва	Barium	<1	0	<1	
В	Boron	62	66	67	
In	Indium		<1		
Sb	Antimony	0	0		
Li	Lithium	<1	<1	<1	

CRACK	(LE TEST				
W	Water	N	N	N	


29.13

29.12

NATER	VALUE (%)	
Vater	Water %	0.0

	OIL CLEANLINESS				
		05-Jun-24	30-Mar-23	30-Jun-20	
PARTIC	CLE COUNT				
ISO4	ISO4	22	21	21	
ISO6	ISO6	18	17	18	
ISO14	ISO14	13	13	14	
4μ	4μ	25969	13864	16207	
6μ	6μ	1674	894	2148	
10µ	10μ	164	151	278	
14µ	14µ	64	63	104	
21µ	21µ	19	21	35	
25µ	25μ	8	11	22	
38µ	38µ	1	2	3	
70µ	70µ	0	0	0	
PQI					
PQI	PQ Index	3	5	5	





NOTICE: This analysis is intended as an aid in predicting mechanical wear and is based upon the supplied information and the results presented in this report. All reported values are tested according to in-house test methods. The results are on an "as received" sample basis. The information supplied by the client is listed in the Sample Information panel of the above report. No guarantee, expressed or implied, is made against failure of this piece of equipment or component.